

# LCD Door Monitor to LBW-420 with AC to DC converter

LBW-420

| LCD Door Monitor   | Ac to DC Converter | LBW-420 Connection |
|--------------------|--------------------|--------------------|
|                    | Blue wire (AC-N)   | J2-N               |
|                    | Brown Wire(AC-L)   | J2-L               |
| Red wire (BL+)     | Red Wire (+VO)     | 4 to 20mA sensor + |
| Black Wire (BL-)   | Black Wire (-VO)   |                    |
| Green Wire(SIG -)  | Black Wire (-VO)   |                    |
| White Wire (SIG +) |                    | 4 to 20mA sensor - |

