

IO-RALHU-50 to LBW-420 with AC to DC converter

LBW-420

Alarm Light and Horn	AC to DC converter	LBW-420 connection
	Blue Wire	J2-N
	Brown Wire	J2-L
RED wire	Red Wire (24VDC +)	
Wht wire (Light)		Pre-Alarm or Alarm NO
GRN wire (Horn)		Pre-Alarm or Alarm NO
	Black wire (24VDC-)	Pre-Alarm or Alarm Relay C

NO = Normally open relay contact
 C = Common relay contact

NOTE: The drawn configuration will cause the light and Horn to come on at high alarm.

Remote Alarm Light and Horn

